


ALARM CONTROL  
(inductances - motor)



**LEGENDA:**

- K1, K2 = motor maneuver
- K3 = out cutter
- VMP = starting solenoid valve
- R = resistor
- C = capacitor
- TS = motor thermistors
- TS1 = inductances thermistor